


Interstate Designation Issues



VERTICAL CLEARANCE DEFICIENCIES

Disclaimer Statement:
This is not a proposal

This is a display of vertical clearance deficiencies for bridge structures if strict Interstate standards were applied.
Future negotiations with the U.S. Department of Transportation may eliminate some or all of the listed locations.



Tag #	PM	Location Description
14	R22.56	Route 99/219 Sep
15	R21.74	Pelandale Ave OC
16	R17.51	Woodland Ave OC
17	R16.79	Kansas Ave OC
18	R16.12	Route 99/132 Sep
19	R16.03	K St OC On-Ramp
20	R16.03	K St OC
21	R15.85	I St OC
22	R15.75	H St OC
23	R15.66	G St OC On-Ramp
24	R15.34	Sierra Dr OC
25	R14.47	Crows Landing Rd OC
26	R13.26	Hatch Rd OC

